JAKKA® TP-3 CE

ТРОСТЕПЕНИ ПРЕКИДАЧ
3 Speeds Switch


ТЕХНИЧКИ ПОДАЦИ


- Волтажа: 230 Vac 50 V 60 Hz
- Макс струја: 3А

ТЕХНИЧКА УПУТСТВА ЗА НАДГРАДНО ПОСТАВЉАЊЕ ТРОСТЕПЕНОГ ПРЕКИДАЧА (IP44)

1 - Благим притиском извуците дугме ❶.
2 - Повежите преко редне клеме ❺ у складу са шемом повезивања.
3 - Уземљите уређај завртњем ❻ који је приложен у кутији.
4 - Убаците прекидач у већу кутију и фиксирајте га завртњима ❹.
5 - Поставите маску ❸ и фиксирајте је завртњима ❷.
6 - Вратите дугме ❶ на своје место.

ОБАВЕШТЕЊЕ: Ако не користите кућиште, прекидач можете директно уградити у зид.





ШЕМА ПОВЕЗИВАЊА

TECHNICAL DETAILS

- Voltage : 230Vac 50/60 Hz
- Max.Current : 3A

INSTRUCTIONS FOR SURFACE ASSEMBLY (IP44)

1 - To take out the button ❶, it goes to pressure.
2 - Connection in the terminals ❺ according to the diagram connection.
3 - Connection the earth, in the screw ❻ located inside to the box.
4 - To insert the small box case inside of the box and to fix it by means of the screws ❹.
5 - Put the cover ❸ and to fix by means of the screws ❷.
6 - Put the button ❶ have a position.

NOTE: If we don't use the external box the group it can be used in built-in version.

RV00

JAKKA®
Bul. Zorana Djindjica 80
11070 Belgrade, Serbia
Tel: +381 11 2600 901
Fax: +381 11 2674 334
www. jakkagroup.com